

PLEASE CAREFULLY INSPECT ALL LUMICOR SHEETS PRIOR TO CUTTING, DRILLING OR FABRICATING. CONTACT LUMICOR AT 1-888-LUMICOR IMMEDIATELY REGARDING ANY DAMAGE OR DEFECT. FAILURE TO DO SO MAY JEOPARDIZE YOUR RIGHTS TO WARRANTY REPLACEMENT AND/OR REIMBURSEMENT FOR SHIPPING DAMAGE.

Lumicor panels are hand crafted using natural materials and are intended for interior use only. The color of encapsulated materials will vary from sheet to sheet and may change color over time.



Liquids and Moisture

The materials encapsulated in Lumicor may wick moisture from the edge of the sheet. If Lumicor products will be installed in a moist environment, the edges must be sealed to prevent wicking. See Lumicor Fabrication Guide at www.lumicor.com/techinfo.



Cleaning

Use warm water, mild soap and a soft sponge or cloth to clean Lumicor. Any acrylic cleaner may also be used. **Do not use glass cleaners, acetone, lacquer thinner, solvents or abrasive compounds.** Do not use squeegees, scrapers or synthetic rags that may scratch the panels.

Handling and Fabrication

Lumicor products ship with a protective masking that should not be removed until fabrication is complete. Most Lumicor products can be fabricated using standard woodworking tools. See fabrication guide at www.lumicor.com/techinfo. Some Lumicor products incorporate glass, metal, or shells that can be fabricated using stone or glass fabrication equipment such as water-cooled stone saws and grinders.

ALWAYS store Lumicor panels on a flat, even surface supported fully across the entire sheet.
ALWAYS confirm the correct Lumicor sheet orientation (front/back and top/bottom) before fabricating.
ALWAYS firmly support the Lumicor sheet and cutting tool to avoid chattering and chipping.
ALWAYS use a continuous flow of air at the cutting tool to dissipate heat during cutting.
ALWAYS use vinyl or nylon grommets and washers with through-bolt fasteners and adequate expansion gaps. See Lumicor Fabrication Guide at www.lumicor.com/techinfo.

NEVER store Lumicor panels in direct sunlight or moisture or in extreme temperatures above 100° F (37° C).
NEVER expose unsealed edges to moisture. Some core materials will wick moisture.
NEVER expose Lumicor material to solvents or solvent vapors.
NEVER over-tighten through-bolt fasteners. This may cause Lumicor products to crack.

DISCLAIMER: We believe this information to be reliable and offer the information in good faith without guarantee, as conditions and methods of use are beyond our control. We recommend prospective buyers perform their own testing to determine product suitability for all purposes before adopting Lumicor on a commercial scale. In no case is Lumicor liable for direct, consequential, economic or other damages. Lumicor disclaims all other warranties, expressed or implied, including the warranty of merchantability and fitness for a particular purpose.